

Geometrics Knowledgebase

USB to Serial Converter configuration for Windows operating system

This article assists in the installation and configuration of a USB to SERIAL converter in order for Geometric's Magnetometers to communicate with a Windows based logging computer.

The document outlines configuration with our G-824 magnetometer but Steps 1-5 are only required when working with any other Geometrics magnetometers. Please scroll down to download the PDF document.

<http://support.geometrics.com/kb/questions.php?questionid=88>